

## Datasheet

| Model                   | Description  | Connection    |
|-------------------------|--|---------------|
| BWA-PRESSURE-SENSOR-50  | Includes pressure sensor PS1G50; 0–50 psi range; gauge; 1/4"-18 NPT port   | 1 meter cable |
| BWA-PRESSURE-SENSOR-150 | Includes pressure sensor PS1G150; 0–150 psi range; gauge; 1/4"-18 NPT port |               |





Figure 1. Model BWA-PRESSURE-SENSOR-50



NOTE: PROTECTIVE VENT COVER AND VENT HOLE ONLY FOR GAGE SENSOR.

Figure 2. Model BWA-PRESSURE-SENSOR-150

| Wire Color | Description |
|------------|-------------|
| brown (bn) | Supply +    |
| blue (bu)  | Supply -    |
| green (gn) | Output      |

## **Specifications**

Supply Voltage

9 V dc to 30 V dc

**Current Consumption** 

< 3 mA

Pressure Range

Proof: 2X FS Burst: 3X FS

Output

0 V dc to 5 V dc

More than 4 million cycles

Accuracy

± 1.0% BFSL

Stability

± 0.25% per Year

Pressure Port

1/4"-18 NPT

Construction

0-50 Model: 304 SS Housing; 316 SS wetting material; Media is compatible with 316 SS 0-150 Model: 304 SS housing; 17-4PH SS wetting material; Media is compatible with 17-4PH SS

**Electrical Connection** 

Conduit Fitting with Cable

Temperature

Compensated: 0 °C to 85 °C (32 °F to 185 °F) Operating: –40 °C to 125 °C (–40 °C to 257 °F)

**Environmental Rating** 

IEC IP65

Zero/Span Offset Tolerance

± 2.5% FS

